Approved Edin Release 2003/02/275 CIA-RDP82-0045776070800890005-0

INFORMATION REPORT

CD NO.

25X1A

COUNTRY	Germany (Russian	Zone)		DATE DISTR.	7 Merch	1952
SUBJECT	Status Report on 25X1C	Eisenhuttenkombinat West, Ca	albe	NO. OF PAGES NO. OF ENCLS.	3	
ACQUIRED DATE OF INFO.		9 NOT C 25X1X	IRCULA	AJEPLEMENT TO	k	
						20.00
1.	construct approval tion and	ary 1952, an inspection commed iron and steel plant at C for operation should be gran analysis of daily loads and or starting the following op:	albe to ted。 Af capaciti	determine whoth ter careful ins es, approval wa	er pec-	
	a. W completio	ood drying fire to be set in n of the pipes (Feldrohre) —	the bla	st furnac ë afte ry 1952.	r the	
		eating the Cowper after the and the drying process - 7 J			la	
	c . T 1952.	rial run of the disintegrato	r with g	as load - 3 Jan	wary	
	d. E	ellows - immediately.				÷
2.	reinspect	ssion was scheduled to meet this equipment and to deter put into operation.				
3.		an analysis prepared by the equipment as of 2 January 1		on of the statu	s of	
	a。 C	onveyor belts and blast furn	ace char	ges.		

Furnace I needs the following amount of cres and fluxes

460 tons.

Document No. _5_ No Change in Class.

Date: 8 SEP 1978

Class. Changed To: TS S

25X1

Declassified

Ore and SII slag ... 190 tons Limestone......120 tons Scrap metal..... 15 tons

Of this amount 310 tons (ore and limestone) are carried on the ore conveyor belt and 150 tons (coke and scrap) are carried on the coke

Total

DISTRIBUTION

Approved For Release 2003/02/27 : CIA-RDF 824 990457 PRO 1708 2001 0005-0

daily:

CLASSIFICATION

NSRB

Approved For Release 2003/02/27: CIA-RDP82-00457R010800010005-0

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

25X1A

- 2 -

conveyor belt. Furnace II has a 25 per cent greater capacity than furnace I, thus making the total daily conveyor belt loads 700 tons for the ore belt and 340 tons for the coke belt. The conveyor belts currently under construction will be able to handle this daily load. At the present time the loading of the conveyor belts is to be handled by portable conveyor belts; arrangements will have to be made for the simultaneous dumping of ore and fluxes from carts onto a permanent conveyor feeding system. The suspension cableways and charges can handle the above loads.

b. Furnace and fittings.

The furnace is ready and a wood drying fire may be started on la January 1952.

c. Cowper and fittings.

The commission observed that the walling-in of the Cowper cupola had not been completed. The deadline was not achieved, and the process will not be finished until 4 January 1952. The gradual heating of the Cowper will only be approved after the electric heaters have warmed the incide of the cupola to a temperature of 100° C. This should be on 7 January 1952.

d. Blast furnace foundations.

The commission noted racks in the foundations of furnace I. The commission recommended that a separate investigating committee be established to investigate the cause of these cracks and those which occurred at Eisenhüttenkombinat Ost. The commission recommended that the foundations of furnace II be banded and that the water gutter be lined with sheet metal.

e. Bellows.

The bellows were examined and found to be in order.

f. Cas purification system.

The commission had certain reservations about starting the disintegrator and the exhauster simultaneously without any automatic pressure control devices, lest a sudden lowering of the pressure cause an intake of air. The commission therefore recommended that only the disintegrator be operated at the present time and that the pressure gauge should be observed at all times and the manual controls be used to reduce the danger of lowered pressure. An automatic pressure control device would have to be installed (either similar to that in Fürstenberg or like the one in Mansfeld) before full operation can be approved.

g. Electric equipment and wiring.

The motor of the disintegrator is rated at 5,000 volts, but can also be operated at 6,000 volts. The load capacity of the wiring system is 6,100 volts. When the three new motors on order arrive from Lützkondorf a re-assessment of the loads and capacity will have to be undertaken.

h. Power supply.

The commission has satisfied itself that there is adequate power to charge both furnaces.

i. Gas supply.

When both furnaces are functioning, there will be an adequate supply of ras for the Cowpers. However, an auxiliary oil heater for the Cowpers must be available, in case one of the furnaces is temporarily shut down.

TON	FIDENTIAL	•	
CENTRAL	INTELLIGENCE	AGENCY	

25X1A

- 3 -

j. Water supply.

There is adequate water supply for the two furnaces (300 cubic meters/hour) and for the ras purification system (150 cubic meters/hour).

k. Utilization of the slag.

Until the granulating process has been set up, there is adequate means of removing the slag by conveyor dump carts even when both furnaces are working simultaneously.

25X1A * Comment: The report does not indicate which of the two furnaces is meant.